




Limitation of Liability: The supplied materials should be thoroughly inspected immediately upon receipt by the recipient for all content, placement and copy accuracy. It is also the responsibility of the recipient printer to examine and proofread all supplied materials before producing image carriers and printing final product. Should the supplied materials be found to be incorrect please contact an SGS representative immediately. The liability of SGS shall be limited to correcting its own product. SGS will not be responsible for any loss or damage including but not limited to the cost of product, print, image carriers, press delays or other ancillary cost.



SGS Client:


FRITO-LAY INC (PKG)

Die:

Limitation of Liability: The supplied materials should be thoroughly inspected immediately upon receipt by the recipient for all content, placement and copy accuracy. It is also the responsibility of the recipient printer to examine and proofread all supplied materials before producing image carriers and printing final product. Should the supplied materials be found to be incorrect please contact an SGS representative immediately. The liability of SGS shall be limited to correcting its own product. SGS will not be responsible for any loss or damage including but not limited to the cost of product, print, image carriers, press delays or other ancillary cost.

Spec ID: BP 303392 Stk 996300

SGS Contact:



LAYOUT RECOMMENDATIONS:

TOP graphics and copy should not extend any further than the "A" position. For minimal distortion on a button closure, try to stay within the "P" position. If copy falls between the "P" and "Q" positions, distortion can occur. For copy on the outer ring of the TOP, recommended print area is between the "Q" and "A" positions.

SIDE copy should fall between the "B" and "D" positions.

Copy and graphics cannot fall past position "D". Overall color of design can extend to "EE".





